

## Lot No. 0175 KLD60Z 60Z20553

Check reports and descriptions serve only as a guide and do not guarantee an exhibit's performance, shape, or quality.

### Basic Information

Mileage	12194	Job Status	General Contractor/Civil Engineering	License Number Plate	None
Cabin/Canopy	Cabin	Cabin Type	Standard	Power Transmission System	Hydrostatic Transmssion
Drive System	All Wheel Drive	Size of Tire	18.4-24-10PR	Type of Tire	Normal
Bucket/Attachment	Loading BK	Others	Heater		

### Appearance

Front Frame	Rusted/Corroded	Counter Weight	Scratched	Cabin/Canopy	Rusted/Corroded
-------------	-----------------	----------------	-----------	--------------	-----------------

### Interior

Seat	Torn	Console	Faded		
------	------	---------	-------	--	--

### Front & Pins

Wear: Bucket Lip	Moderate/Within Service Limit	Wear: Bucket Bottom Plate	Excessive/Need Repair		
------------------	-------------------------------	---------------------------	-----------------------	--	--

### Oil/Water/Air Leak

Oil Leak: High Pressure Pipes	Slight Film	Oil Leak: Transmission/Torcon	Slight Film		
-------------------------------	-------------	-------------------------------	-------------	--	--

### Undercarriage/Chassis/Tires

Oil Leak: Differential Gear Case	Slight Film				
----------------------------------	-------------	--	--	--	--

### Overall Rating

Appearance Evaluation	Fair	Rust/Corrosion	Moderate		
-----------------------	------	----------------	----------	--	--